

# 13 Square de Lorient, Melun

oct-23

Enquête Sociale Le Frêne

Etages	Typologies							
	T1	T3	T3	T1	T1	T3	T3	T1
14	1401	1402	1403	1404	1405	<b>1406</b>	1407	1408
13	1301	1302	1303	1304	1305	1306	1307	1308
12	1201	1202	1203	1204	1205	1206	1207	1208
11	<b>1101</b>	1102	1103	1104	1105	1106	1107	1108
10	1001	1002	1003	1004	1005	1006	1007	1008
9	901	902	903	<b>904</b>	905	906	<b>907</b>	908
8	801	802	803	804	805	806	807	808
7	701	702	703	704	705	706	707	708
6	601	<b>602</b>	<b>603</b>	604	<b>605</b>	606	<b>607</b>	<b>608</b>
5	501	502	503	504	505	<b>506</b>	507	<b>508</b>
4	401	402	<b>403</b>	404	405	406	407	408
3	301	302	<b>303</b>	304	305	<b>306</b>	307	308
2	201	<b>202</b>	<b>203</b>	204	205	206	207	208
1	101	102	103	<b>104</b>	105	106	107	108

 Logements Occupés 12 lgts

 Logements vides 7 lgts


 Logements Diagnostiqués 15 lgts

 bt pour neutralisation OK 0 lgts

 Logements Murés - Plaqués (y compris :

>retrait compteur elec et eau

>condamnation Fenêtre et Sanitaire)

 problème de clefs 2 lgts

---

112 lgts

1403-1404 & 1405 équipements déposés mais porte non neutralisées car purgeurs chauffage

13LDL1401 els le 22/04/2022